


AMB6 Stop delivery - Inspect seat belt and replace if necessary



AMB6 Stop delivery - Inspect seat belt and replace if necessary

IMPORTANT REMINDER

IT IS A VIOLATION OF FEDERAL LAW FOR DEALERS TO DELIVER TO CUSTOMERS NEW VEHICLES IN THEIR INVENTORY AFFECTED BY THIS NOTIFICATION UNTIL THESE VEHICLES ARE REMEDIED. DEALERS SHOULD

NOT SELL, LEASE, RENT, OR LOAN ANY NEW OR USED VEHICLES IN DEALER INVENTORY AFFECTED BY THIS NOTIFICATION PRIOR TO REMEDY. DEALERS GROUNDING LEASE RETURNS SHOULD REMEDY ALL AFFECTED GROUNDED VEHICLES.

Update 8/11

The remedy check for affected vehicles is posted below. There are 3 different remedy documents, please choose the correct instructions for the model at your dealer.

Please note - This is only a check to see if the seat belts need to be replaced.

The Stop Delivery can be lifted via a Warranty Claim if the check is performed and the belts do not need to be replaced. If this is the case, Scope 1 can be claimed for Warranty processing of the Cayenne, Panamera, and 992. Scope 2 will need to be claimed for the Taycan.

If the belt is not functioning as designed and needs to be replaced then the Stop Delivery must remain on the vehicle until the belts are replaced.

Overview

A seat belt assembly supplier reported that seat belt assemblies in the subject vehicles may not meet one of the applicable Federal safety standards.

Accordingly, the seat belt assemblies must be inspected, and replaced if necessary.

Model type	911 (992) Taycan (Y1A) Panamera (971) Cayenne (9YA/9YB)
Model year	2021
Number of affected vehicles	167

Vehicle usage

The vehicles may only be driven for loading and unloading purposes in the transport chain.

AMB6 Stop delivery - Inspect seat belt and replace if necessary

Further use is not permitted. Test drives are to be omitted.

Test instructions and remedial measures

Will be communicated once available (Est. Calendar Week 32).

Please inform all relevant dealer staff of this communication immediately.