

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS6103
URGENT - DISTRIBUTE IMMEDIATELY

Date: March 28, 2022

Subject: REVISION: N212330130-02 – Safety Recall
Rear Suspension Toe Link May Break
Revised Service Procedure

Models: 2013 Buick LaCrosse
2013 Buick Regal
2013 Chevrolet Malibu

To: All General Motors Dealers

This bulletin is being revised to update the Service Procedure. Please discard all previous copies of N212330130.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS