

From: [Polaris Service](#)
To:
Subject:
Date:

Trouble viewing this email?



Date: September 15, 2021
Attn: Indian Motorcycle Dealers
Subject: Safety Recall I-21-03 Released

Key Actions & Timing: Please Read

Questions: Contact Indian Motorcycle Technical Service

Dear Indian Motorcycle Dealer,

Please review the following communication that was posted on Wednesday, 09/15/2021.

Indian Motorcycle has identified a potential concern with brake light function on a small number of model year 2020 Scout Bobber Sixty models. These models may exhibit a loss of brake light functionality following an engine controller update during service. Loss of rear brake light functionality could reduce rider visibility, increasing the risk of a crash.

To address this concern, Indian Motorcycle is requesting customers to inspect their brake lights for proper functionality – and if nonfunctional to contact a dealer for repair.

· Click [HERE](#) to view I-21-03

Thank you for your attention.

Sincerely,
Indian Motorcycle Service

This email was sent by Polaris Inc. to

[Privacy Policy](#)

© 2021 Polaris Inc.
2100 Highway 55, Medina, MN 55340, USA | [Polaris.com](#)