


# AMB9 Recall Campaign – Reworking brake booster



## AMB9 Recall Campaign - Reworking brake booster

### Overview

On the affected vehicles, there is a possibility that the screw connection of the pressure input rod of the brake booster was not carried out according to specifications.

As a result, the pressure input rod may become detached from the brake booster over the running time of the vehicle. If the pressure input rod is detached, it is not possible to brake the vehicle using the brake pedal. The emergency braking function via the electric parking brake is still available without restriction.

To avoid possible detachment of the pressure input rod, the affected bolted joint connection will be checked and, if necessary, the brake booster will be replaced/repaired.

<b>Model type</b>	911 (992)
-------------------	-----------

AMB9 Recall Campaign – Reworking brake booster

	Taycan (Y1A/ Y1B)
<b>Model year</b>	2020 to 2021
<b>Number of affected vehicles</b>	11

## Porsche Mobility

Immediate towing of the customer's vehicle to the dealer and a service loaner should be offered to all affected customers until such time as the repair is complete.

## Warranty processing

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Scope 1: **Taycan (Y1A / Y1B)**

Damage Code	<b>AMB9 99 000</b>
Repair Code	1
Working time	<b>44 TU</b>

**The scopes will be completed as soon as the remedial measure for 911 (992) is available.**