

GLOBAL SAFETY FIELD INVESTIGATIONS  
DCS6058  
URGENT - DISTRIBUTE IMMEDIATELY

Date: February 23, 2022

Subject: REVISION: N212349040-01 - Safety Recall  
Driver Front Airbag Inflator May Rupture  
Revised Correction and Service Procedure

Models: 2008-2017 Buick Enclave  
2013-2017 Chevrolet Traverse

To: All General Motors Dealers

The correction statement and service procedure have been updated in this bulletin. Please discard all previous copies of N212349040.

**(TECHNICIAN and WARRANTY ADMINISTRATOR) SERIAL NUMBER  
RECORDING REQUIREMENT.**

**The removed and replacement Steering Wheel Airbag assembly serial numbers must be captured by the technician and recorded on the job card.** The Warranty Administrator MUST enter the replacement steering wheel airbag assembly serial number in GWM (Global Warranty Management) or in DMS (Dealer Management System). Enter the serial number of the replacement steering wheel airbag in the 'Labor Operation Dependency Code' field (1) per the screen above. Enter the serial number of the removed steering wheel airbag in the 'General Comments' comments section. Failure to enter these serial numbers will cause the claim to reject.

**Question and Answer Document (Q&A)**

Attached to this message you will find an updated document that addresses the ten most likely questions customers may have regarding this Safety Recall. Please use this information as an aid to confidently answer customer concerns.

END OF MESSAGE  
GLOBAL SAFETY FIELD INVESTIGATIONS