


# AMC1 Stop Delivery - Hazard Warning Lamp – automatic activation re-programming



## AMC1 Stop Delivery - Hazard Warning Lamp - automatic activation re-programming

### Vehicle blocking - Stop Delivery

Please do not deliver the subject vehicles to customers until the remedy is performed.

### Overview

The subject vehicles are programmed with pre-collision automatic hazard warning lamp activation logic that exceeds the automatic activation functionality permitted by FMVSS No. 108. To remedy this incompatibility with the applicable regulation, the subject vehicles will be reprogrammed to remove the function.

<b>Model type</b>	Taycan (Y1A / Y1B)
<b>Model year</b>	2020-2022

**Number of affected vehicles**

286

## **Vehicle usage**

The vehicles may only be driven for loading and unloading purposes in the transport chain.

Any further use is not permitted. Test drives are to be omitted.

## **Test instructions and remedial measures**

The re-programming instructions will be communicated once available.