


RECALL 21V219 REMEDY INSTRUCTIONS

	Make(s): Berkshire Model(s): Many, See Below Model Year(s): 2021	Repair Code: RC-055-03-00-004010 Allotted Time: .10 HRS Inspection Code: N/A Allotted Time: N/A
	Concern: The rear taillights do not meet F/CMVSS 108 Reflective Requirements.	Photo(s) Required: NO Prior Authorization Required: NO Part(s) Kit Number: F100259070 – QTY: 2 Part(s) Return: N/A

Ensure the vehicle is in Park and the Parking Brake is engaged. Block tires to prevent the vehicle from rolling. Failure to do so may result in personal injury, property damage and/or death.

Models affected: BEA37A-380, BEA40C-380, BEA40D-380, BEA40E-380, BEA45A-450 and BEA45CA-450.

STEP 1: REFERENCE THE PHOTO BELOW OF THE REAR CAP (FIGURE 1);

STEP 2: CLEAN THE CAP SURFACE EXTREMELY WELL ON THE REAR CURB SIDE AND REAR ROAD SIDE (AS DEPICTED IN THE PICTURE BELOW) WHERE THE STICK ON REFLECTORS WILL BE INSTALLED;

STEP 3: PEEL THE BACKING OFF THE REFLECTOR DOUBLE SIDED TAPE, ORIENTATE THE REFLECTOR (AS DEPICTED IN THE PICTURE BELOW) AND PRESS THE REFLECTOR FIRMLY AGAINST THE CAP, HOLDING IN PLACE FOR A SHORT TIME TO PROMOTE COMPLETE ATTACHMENT;

STEP 4: REPEAT STEP 3 ON THE OPPOSITE SIDE, THEN CLAIM THE REPAIR CODE LISTED ABOVE.

FIGURE 1



ROAD SIDE
DRIVERS SIDE

NEWLY INSTALLED REFLECTORS
(REAR OF VEHICLE)

CURB SIDE
PASSENGERS SIDE