

L636-
R.03.21

To: **After Sales Official Network**
Subject: **Engine replacement**
Date: **25 June 2021**
Pages: **3**



Campaign code:

L636-R.03.21

Campaign name:

Engine replacement

Model:

Urus

Model Year:

2021

Limited or special editions:

All

Markets:

USA, Germany, Romania and Saudi Arabia.

VIN Identification:

From to MLA11325 to MLA12169

ZPBEA1ZL6MLA12169
ZPBUA1ZLOMLA11546
ZPBUA1ZL4MLA11405
ZPBUA1ZL7MLA11530
ZPBEA1ZLOMLA11597
ZPBEA1ZL6MLA11538
ZPBUA1ZL6MLA11325


Important information: before proceeding with the repair, connect to the Warranty Portal and, using the "VIN Info" function, check that:

- the vehicle is actually affected by the instructions contained in this bulletin.

NOTE: some vehicles may not be affected, despite the fact that their Vehicle Identification Number (VIN) falls within the range;

- only replacement parts that correspond to the specific procedure, identified by a letter (such as A, B, C, etc.), are to be used for the chassis being repaired.

Example



N.B.:

Procedure A will be available only when the instructions require a preliminary check to be performed to determine whether or not the vehicle actually needs updating.

Information for the service network:

During ongoing product monitoring, Automobili Lamborghini S.p.A. has discovered that on a specific number of vehicles there is a possibility that cracks could occur on the running surface of the cylinder 6' bore.

Solution for the field:

Replace of the engine following the instruction below.

Spare Parts:

OPTION B

Part number	Description	Q
OP2100021S	ENGINE, COMPLETE	1

Management of replaced parts:



IMPORTANT:

After replacement, the old engine must be sent to Automobili Lamborghini HQ.



Labor time:


Operation B: 31,7 h

Previous bulletins superseded.

None.

Warranty claim instructions:

To request reimbursement for the repair performed, access the "LIASS" system on the Lamborghini portal and, following the instructions in the system's "Manuals" section, generate and fill out a Warranty Request. Select the required campaign and proceed with entry; carefully read the options present in the alert message that displayed by the system (see example) and select the option performed on the vehicle.



Reimbursement will be structured as follows, on the basis of the operation performed:

- **OPTION B: Engine replacement**
 - o *Labour time: 31,7 h*

Important information:

attach all documents generated during the work carried out, evidence of the work itself, for instance work orders and diagnostic protocols with BETA-Reports.

If one or more of these is missing, it may lead to a rejected reimbursement request.

Fill out the page in the warranty booklet (identified in the image below) in the section "Service and Recall Campaigns":

Tools/Materials required

Code	Description.	Q.
VW TL 774-L	Pakelo LM-P Ready Coolant 50 (code 1899.S0) READY TO USE FROST PROTECTION -38 °C (-36 °F)	13 L
SAE 0W-40 Porsche C40 VW 511 00	Engine oil	11 L



N.B. (*)

All ODIS technical documentation can be viewed on the Lamborghini web portal, in the ODIS section.



Repair method:

1. To replace the engine follow the instructions on the workshop manual at the path:

O1 Engine → Engine Assembly → Engine EA825 → Disassembly/Assembly



IMPORTANT:

The documents which must be provided together with the operation under warranty request are:

- *Produced Repair Order*
- *Saved Diagnostic Protocol with BETA report*

Failure to follow these procedures could lead to the request being rejected.

For more information, please contact your Area Manager or write to Technical Support (service.department@lamborghini.com).