

Service Bulletin

21-056

May 29, 2021 Version 1

Safety Recall: 2022 Odyssey Second Row Outer Seats

AFFECTED VEHICLES

Year	Model	Trim	VIN Range
2022	Odyssey	ALL	Check the iN VIN status for eligibility.

BACKGROUND

The second row outer seat(s) rail may have been damaged during assembly causing the seat(s) to remain unlatched. An unlatched seat(s) can move unexpectedly under certain braking conditions which may lead to injuries. Failure to repair a vehicle as necessary prior to sale may subject your dealership to claims or lawsuits.

When this temporary placeholder bulletin appears during an iN VIN status inquiry or eResponsibility report, this vehicle is subject to a Safety Recall. This vehicle is on **STOP SALE** until further notice. Check for an iN message for further details. Refrain from calling Tech Line for updates.

This bulletin will be updated once Parts Information, Warranty Claim Information, Inspection Procedures, and Repair Procedures are available.

END

CUSTOMER INFORMATION: The information in this bulletin is intended for use only by skilled technicians who have the proper tools, equipment, and training to correctly and safely maintain your vehicle. These procedures should not be attempted by "do-it-yourselfers," and you should not assume this bulletin applies to your vehicle, or that your vehicle has the condition described. To determine whether this information applies, contact an authorized Honda automobile dealer.