

H365NAS1

TECHNICAL BULLETIN

30 JUL 2021



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

SECTION:

100-00

SUBJECT/CONCERN:

Instrument Panel - Renew

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:
F-TYPE (X152)	2018	K55726

MARKETS:

USA

CONDITION SUMMARY:

SITUATION:

A potential issue has been identified on certain vehicles within the listed Affected Vehicle Range where the passenger airbag deployment door, integrated in the instrument panel, contains an additional mesh layer.

ACTION:

Retailers are required to HOLD affected new vehicles that are within your control and refrain from releasing the vehicles for new vehicle sale pending completion of the procedure(s) detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but must have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

TOOLS INFORMATION:

Refer to TOPIx Workshop Manual/Service Instruction(s) for any required special tools.

PARTS INFORMATION**NOTE:**

Use the Vehicle Identification Number (VIN) and the Electronic Parts Catalogue (EPC) to confirm part number(s) necessary to perform repairs.

The parts below should be ordered through Jaguar Land Rover (JLR) in the normal manner.

DESCRIPTION	PART NUMBER	QTY
Instrument panel	T2R3397PVJ	1

SROS

DESCRIPTION	SRO	TIME
Instrument Panel - Renew	99.02.01.42	2.8

DESCRIPTION	SRO	TIME
Drive in/drive out	10.10.10	0.2

NOTE:

Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to TOPIx to obtain the latest repair time.

WARRANTY INFORMATION

Warranty claims should be submitted quoting program code H365 with the relevant option code from the table below. As option codes are used there is no requirement for you to enter SROs or parts, these are included for information only.

PROGRAM CODE	OPTION	VIN	DESCRIPTION	SRO	TIME	PART NUMBER	QTY
H365	A	SAJDD1GX3JCK55726	Instrument Panel - Renew	99.02.01.42	2.8	T2R3397PVJ	1
H365	B	SAJDD1GX3JCK55726	Instrument Panel - Renew Drive in/drive out	99.02.01.42 10.10.10	2.8 0.2	T2R3397PVJ	1

Warranty claims should be submitted in accordance with the current **JLR** Global Warranty Manual, and its amendments, unless stated otherwise in this bulletin.

Claims for related damages can only be made when this bulletin has been paid/accepted.

Claims should be submitted quoting program code H365 and by clicking the 'Related Damage' radio button on the claim submission screen.

SERVICE INSTRUCTION

1. Renew the instrument panel (see TOPIx Workshop Manual section 501-12: Instrument Panel and Console - Removal and Installation - Instrument Panel).