

Recall Inspection and Repair Instructions

NHTSA Recall #: 21V-514

Tiffin Recall #: WAY-100

Models Involved: 2017, 2018, 2019, 2020, & 2021 all floor plans with standard wheels

Tools Needed:

Small crow bar or pry tool

Parts Needed:

None at this time

FLAT RATE CODES AND TIMES

When filing the warranty claim for payment please use the following flat rate codes and times.

WF8801RC01, for 0.25 hours.

Inspection Procedure:

1. Verify the unit is equipped with the standard Wayfarer wheel liner as shown below.

Standard Wheel Liner – **Involved**



Upgraded wheel liner, **NOT involved**



Repair Procedure:

1. Insert a small crow bar or pry tool on the edge of the standard Wayfarer wheel liner and apply slight pressure to the edge of the wheel liner. The wheel liner will pop loose. Remove and store the wheel liner until the repair is available.



2. Inspect the valve stems for any signs of damage or wear due to contact with the wheel liner. If damage is found, please contact Wayfarer warranty department at 205-487-4710.