
Aftersales TSO – Recall Campaign



MAS002857
(MTB 21-12)

From: Aftersales – TSO
To: Maserati Dealer Network
Auburn Hills, MI.
November 19, 2021

Recall Campaign # 442 – U.S.

M15x V8 - M161 V8 - M240 - Replacement of fuel line sensor housing

NOTE: Before starting this procedure, you MUST read these instructions carefully and completely.

MASERATI SAFETY RECALL NOTIFICATION

PERFORM THE PROCEDURE OUTLINED IN THIS TECHNICAL BULLETIN ON ALL AFFECTED VEHICLES BEFORE CUSTOMER DELIVERY OR THE NEXT TIME THE CAR IS IN THE SHOP FOR MAINTENANCE OR REPAIRS.

Maserati S.p.A. and Maserati North America, Inc. (MNA), have decided that a defect that relates to motor vehicle safety exists in certain 2021 Model Year (MY) Maserati Quattroporte and Ghibli vehicles, 2021 MY and 2022 MY Levante vehicles and 2022 MY MC20 vehicles.

Description of Vehicle Safety Recall #442

Maserati S.p.A. and MNA have determined that the above-described vehicles may contain a safety defect in the fuel line sensor housing that may crack and leak fuel. The fuel line sensor fuel leak may cause fuel starvation of the engine. In rare circumstances, if the leaked fuel comes in contact with an ignition source, a fire could occur. Fuel starvation may result in an unexpected loss of motive power, which can cause a vehicle crash without prior warning. A vehicle fire can result in increased risk of occupant injury and/or injury to persons outside the vehicle, as well as property damage.

The remedy is to introduce a specific procedure to replace the fuel line sensor housing.

This repair procedure will be performed free of charge to the vehicle owner.

Which Vehicles Are Affected

Please refer to the VIN List in ModisCS+ for the affected vehicles.

Vehicle Remedy Information

1. Check that the vehicle is included in this Recall Campaign, and that the repair has not been previously performed.
2. Replace the fuel line sensor housing following the below procedures listed in the Workshop Manuals.
 - **01.43.080 - ENGINE COMPARTMENT FUEL PIPING (M15x)**
 - **01.43.080 - ENGINE COMPARTMENT FUEL PIPING (M161)**
 - **01.43.149 - FUEL DELIVERY PIPING ENGINE COMPARTMENT (M240)**

Parts Needed For The Recall

For this Recall Campaign, the fuel line sensor housing is made to order and is VIN specific. Please only order if you currently have a car on your lot or if you have scheduled the customer into your workshop for repair.

The process to request the fuel line sensor housing is as follows:

3. Open a PHD using category "Other"
4. In the PHD mention this is for Campaign #442
5. Provide the VIN number or you can list multiple VIN numbers
6. Provide the part number you require

MNA dealer services team will confirm the VIN(s) provided are part of the campaign and enter the order the same day.

Description	Part Num.
Sedans (M156, M157)	670153442
Levante (M161)	670103708
MC20 (M240)	670156467

Warranty Information:

Description	Code
Campaign Number	442
Warranty Code	24
Fault Code	063
Component Code	01.43.080
Labor Operation Code	
<i>Sedans</i>	01.43.080.A (1,25)
<i>Levante</i>	01.43.080.B (1,15)
<i>MC20</i>	01.43.080.C (0,75)

If you have any questions, contact your Regional AfterSales Manager or the Technical Support Helpdesk.

Thank You for your continued support and cooperation.

Maserati North America Inc.
Aftersales Dept.