

REPAIR INSTRUCTIONS
KZ RECALL
NHTSA 21V-992
Transport Canada 2021-780
Internal KZ-2021-08

211MKSE Gas Line Relocation

The vehicles subject to this recall were manufactured with the LP gas line routed through the wheel well in too close proximity to the tire tread path. Inspect the LP gas line in the wheel well as shown below. If the gas line is less than 12" from the tire tread it must be relocated as described below.

KZ Flat Rate Code- #7782-C211MKSE

Time allotted- 1 hr.

1. Open slide, remove original screw from existing spring.
2. Re-secure the spring to the frame, making sure to be 12" from tread of tire.





Current distance from tread 8"