



July, 2024

***** IMPORTANT SAFETY RECALL REMINDER *****

According to our records, your 2010 MKX has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

Recall Number and Description: **21S05 - Takata Service Parts**

What is the issue?

Our records indicate that a safety recall repair was previously completed on your vehicle to replace the passenger airbag in January 2019 and that the passenger airbag was later replaced during a collision or service repair. The replacement airbag(s) installed at that time may contain a defective airbag inflator.

Defective airbag inflators may explode in a crash that causes deployment of the airbags. If an inflator explodes, sharp metal fragments could strike vehicle occupants, causing serious injury or death.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**. If you wish to contact us through the Internet, our address is: lincoln.com/support.

Thank you for your attention to this very important matter.

Julio de, 2024

***** RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD *****

SegUR nuestros registros, no se realizaron en sur 2010 MKX las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

Número y descripción de la campaña: **21S05 - Piezas de servicio Takata**

¿Cuál es el problema?

En nuestros registros aparece que en su vehículo se realizó una reparación de la campaña de seguridad para reemplazar las bolsas de aire del pasajero en enero de 2019 y que dicha bolsa de aire se reemplazó posteriormente durante una reparación de servicio o por colisión. La bolsa de aire de reemplazo instalada en ese momento podría incluir un inflador de la bolsa de aire defectuoso.

Los infladores de la bolsa de aire defectuosos podrían detonar en un choque y provocar el despliegue de las bolsas de aire. Si detona un inflador, se podrían desprender fragmentos de metal filudos, los cuales podrían golpear a los ocupantes del vehículo y provocarles lesiones graves o incluso la muerte.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**. Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: lincoln.com/support.

Gracias por su atención en este asunto sumamente importante.




THE LINCOLN MOTOR COMPANY

P.O. BOX 1904
DEARBORN, MI 48121-1904

Presorted STD
US Postage
PAID
R K C

1007102 A / 000000000000118 / 118



SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR
OPENING INSTRUCTIONS

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

▶ REMOVE THESE SIDE EDGES FIRST
THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶

