

IMPORTANT SAFETY RECALL

This notice applies to your vehicle, VIN:

NHTSA Recall # 21V-306

Tiffin Recall # TIF-116

Cummins Recall # C2423

August 27, 2025

Cummins L9 engine, fuel rail assembly may leak

This is a reminder that your motorhome has an open safety recall. If this recall does not apply or has already been completed, please email recalls@tiffinmotorhomes.com.

VIN:

ESN:

ISD:

Dear Tiffin Motorhome Owner,

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Tiffin Motorhomes has decided that a defect, which relates to motor vehicle safety, exists on the following models of motorhomes: **2017, 2018, 2019, 2020 and 2021 Allegro Bus motorhomes built on PowerGlide chassis and 2017, 2018, 2019, 2020 and 2021 Phaeton motorhomes built on PowerGlide chassis that were built between March 1, 2017, and February 28, 2021.**

Tiffin Motorhomes was notified by Cummins, Inc of a defect that exists on specific L9 engines manufactured between January 2, 2017, and October 16, 2020. The fuel rail assembly on these engines may develop leaks, which may result in an undetected prolonged diesel fuel spray. The owner/operator may see or smell diesel fuel and, in some cases, the check engine lamp may illuminate. A leak involving spraying/misting fuel in the presence of an ignition source may increase the risk of fire.

Cummins will correct this condition by inspecting the rail threads for damage and, if damage is found, replace the rail and fuel lines. If no damage is found, new crush washers will be installed in the rail assembly using a special tool. This repair is currently available at Cummins Distributors and authorized Warranty Dealers. The repair will be completed free of charge and most applications will require approximately 2.5 hours to complete. Please contact the nearest Cummins Distributor or authorized Warranty Dealer to arrange to have this campaign performed on your engine. The distributor or dealer will work with you to schedule the best date to complete

this repair. Cummins will need both the ESN and ISD for your motorhome, that information is located at the top of this notification.

In the meantime, Cummins advises you to periodically check the fuel rails for signs of leaking and seek repairs if leaks are identified. If a leak occurs the operator may see or smell diesel fuel and, in some cases, the check engine lamp may illuminate.

If you have questions or concerns about this recall, please contact your local Cummins Distributor or authorized warranty dealer. You may also contact Cummins Care at 1-800- CUMMINS (1-800-286-6467) or visit their website at care.cummins.com.

If you do not own the vehicle that corresponds to the identification number which appears on this Recall Notification, please return the notification to the Tiffin Warranty Department with any information you can furnish that will assist us in locating the present owner. You may also call us at 256-356-8661 ext. 2176 or email recalls@tiffinmotorhomes.com.

If, after contacting Cummins, you have further questions, please contact the Tiffin Recall Department, at 1-256-356-8661, 8:00 a.m. to 3:30 p.m., Central Time. You may also wish to notify the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue SE, Washington DC 20590, or phone 1-888-327-4236 (TTY: 1-800-424-9153): or go to <http://www.safercar.gov>.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

We regret any inconvenience this action may cause, but feel certain you understand our interest in motor vehicle safety.

Tiffin Recall Department