



December, 2024

**\*\*\* IMPORTANT SAFETY RECALL REMINDER \*\*\***

According to our records, your 2021 F-150 Ford Truck has not had necessary safety recall repairs made. We urge you to have the free repair performed at your local dealership as soon as possible.

**Recall Number and Description:** **21S25 - Rear 2-Piece Driveshaft Disconnection**

**What is the issue?** On your vehicle, an improperly assembled two-piece driveshaft may have been installed. The circlip used to secure the connection between the two driveshaft halves may not have been properly installed, potentially affecting connection of the two halves.

Separation of the driveshaft can result in a loss of motive power without warning while driving, or unintended vehicle movement in park if the parking brake is not applied, increasing the risk of a crash. You may hear a loud clunking or banging noise while driving or experience that the vehicle is only capable of moving in 4WD.

If you have questions or concerns, please contact our **Ford Customer Relationship Center at 1-866-436-7332**.

If you wish to contact us through the Internet, our address is: [ford.com/support](http://ford.com/support).

Thank you for your attention to this very important matter.

December de, 2024

**\*\*\* RECORDATORIO IMPORTANTE PROGRAMA DE SEGURIDAD \*\*\***

SegUR nuestros registros, no se realizaron en sur 2021 F-150 Ford Truck las reparaciones necesarias correspondientes a la campaña de seguridad. Le solicitamos que realice esta reparación gratuita en su distribuidor local lo antes posible.

**Número y descripción de la campaña:** **21S25 - Desconexión de la flecha de mando trasera de 2 piezas**

**¿Cuál es el problema?** Es posible que en su vehículo se haya instalado una flecha de mando de dos piezas incorrectamente ensamblada. El clip circular utilizado para asegurar la conexión entre las dos mitades de la flecha de mando podría no haberse instalado correctamente, lo cual podría afectar la conexión de las dos mitades.

La separación de la flecha de mando podría ocasionar una pérdida de la fuerza motriz sin advertencia mientras maneja o un movimiento involuntario del vehículo cuando está en Estacionamiento, si el freno de estacionamiento no está aplicado, lo cual aumenta el riesgo de choque. Es posible que escuche un ruido de tronido fuerte o golpeteo mientras maneja o que experimente que el vehículo solo se puede mover en 4WD.

Si tiene dudas o preguntas, comuníquese con nuestro **Centro de Relación con Clientes Ford al 1-866-436-7332**.

Si desea ponerse en contacto con nosotros a través de Internet, nuestra dirección es: [ford.com/support](http://ford.com/support).


Gracias por su atención en este asunto sumamente importante.



P. O. BOX 1904  
DEARBORN, MI 48121-1904

Presorted STD  
US Postage  
**PAID**  
R K C

0744517 A / 000000000000376 / 376



SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

SEE OTHER SIDE FOR  
OPENING INSTRUCTIONS

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶  
REMOVE THESE SIDE EDGES FIRST

▶ THEN FOLD, CREASE AND TEAR THIS STUB ALONG PERFORATION ▶  
REMOVE THESE SIDE EDGES FIRST

