



Your vehicle has a safety recall!

LICENSE PLATE
MAKE/MODEL
VIN

RECALL / RETIRO

Potential Increased Risk of Vehicle Fire (21TA06)

DESCRIPTION / DESCRIPCIÓN

The subject vehicles are equipped with halogen headlamps that allow the circuits for both the high and low beam bulb filaments to be energized at the same time when the high beams are switched on.

RISK / RIESGO

Under some conditions, if the high beams are repeatedly left on for an extended period while the vehicle is idling or driving at low speed, there is a possibility that the bulb connector could overheat to a level that can result in an increased risk of a fire that can propagate to other parts of the vehicle.

FIX / SOLUCIÓN



Scan this QR code to find a local authorized dealer that will modify the engine wire harness assembly and inspect the headlight components, replacing components as needed, FREE OF CHARGE OR CALL 800-331-4331.

This program is sponsored by Toyota Motor North America and is powered by Carmo Project.



U.S. Department of Transportation



Safety is our mission. Learn how this notice got to your car at carmoprotects.com.

Hablamos Español



Su vehículo se ve afectado por una CAMPAÑA DE SEGURIDAD URGENTE!