

Subject:

Model 3 Trunk Lid Harness Retrofit



Tesla has decided to proactively recall model year 2017-2020 Model 3 vehicles to inspect and retrofit the trunk lid harness. Our records indicate that your vehicle(s), <VIN>, may be affected by this recall.

On certain Model 3 vehicles, the trunk lid harness is equipped with a solid core coaxial cable that provides the rearview camera feed for visibility on the center display. Over time, repeated opening and closing of the trunk lid may cause excessive wear to the coaxial cable. If the wear causes the core of the coaxial cable to separate, the rearview camera feed is not visible on the center display. Unavailability of the rearview camera display may affect the driver's rear view. We are not aware of any crashes or injuries relating to this condition.

No immediate action is required if you own a Model 3 vehicle affected by this recall. If you experience a loss of rearview camera display, you may continue to operate the vehicle by performing a shoulder check and using your mirrors when backing. Tesla will contact you to schedule a service appointment when parts become available in your region and inspect and retrofit your vehicle, all free of charge.

Thank you for being a Tesla customer, and we apologize for this inconvenience.