

TOPIC	TYPE	RECALL CODE	QUESTION	ANSWER												
Safety Recall 40Q7	Safety Recall	40Q7	What vehicles are included in Safety Recall 40Q7?	<table><tr><th>Country</th><th>Beginning Model Year</th><th>Ending Model Year</th><th>Vehicle</th></tr><tr><td>USA</td><td>2021</td><td>2021</td><td>ATLAS</td></tr><tr><td>USA</td><td>2020</td><td>2021</td><td>ATLAS CROSS SPORT</td></tr></table>	Country	Beginning Model Year	Ending Model Year	Vehicle	USA	2021	2021	ATLAS	USA	2020	2021	ATLAS CROSS SPORT
Country	Beginning Model Year	Ending Model Year	Vehicle													
USA	2021	2021	ATLAS													
USA	2020	2021	ATLAS CROSS SPORT													
			What is the safety concern for Safety Recall 40Q7?	A front steering knuckle may fracture in the area of the strut mounting. A steering knuckle that fails while driving may lead to a loss of vehicle control without warning, which can increase the risk of a crash.												
			What is the repair for Safety Recall 40Q7?	To identify/correct this defect, your authorized Volkswagen dealer will inspect and, if necessary, replace the steering knuckle(s). The inspection will take up to two hours. Replacement, if necessary, may take up to half a day to complete and will be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the repair, as well as to accommodate their daily workshop schedule.												
			When will the repair for Safety Recall 40Q7 be available?	Parts are available now and repairs have begun. Please contact your authorized Volkswagen dealer without delay to schedule this recall repair. To set up an appointment online, please visit www.vw.com/find-a-dealer .												