


## CAMPAIGN LAUNCH STATUS

### N556 AND H332 SAFETY COMPLIANCE RECALLS



#### SAFETY COMPLIANCE RECALLS N556 and H332 AUTO HIGH BEAM ASSIST LAMP MISSING

AFFECTED MODELS	19-20MY F-PACE; 18-20MY Range Rover, Range Rover Sport, RR Velar, Discovery with High line TFT instrument cluster
VOLUME AFFECTED	N556 - 26,805 USA 2,544 CAN H332 - 455 USA 110 CAN
REPAIR	 <p>The Auto High Beam (AHB) system does not indicate in the instrument cluster the high beam is being operated automatically. Vehicles in this condition do not meet the requirements of Federal Motor Vehicle Safety Standards. Affected vehicles will require an instrument cluster software update with Pathfinder</p>
REPAIR TIME	0.3hrs + DIDO
CAMPAIGN LAUNCH	Target March 17 <sup>th</sup> 2021
Notes	Retailer notification and stop sale March 11 <sup>th</sup> , 2021 220 affected units in retailer inventory require repair before sale. Customer mailing will be completed by April 23 <sup>rd</sup> , 2021



PRINTED COPIES ARE UNCONTROLLED