

TOPIC	TYPE	RECALL CODE	QUESTION	ANSWER												
Safety Recall 44Q9	Safety Recall	44Q9	What vehicles are included in Safety Recall 44Q9?	<table border="1"> <thead> <tr> <th>Country</th> <th>Beginning Model Year</th> <th>Ending Model Year</th> <th>Vehicle</th> </tr> </thead> <tbody> <tr> <td>USA</td> <td>2021</td> <td>2021</td> <td>ATLAS</td> </tr> <tr> <td>USA</td> <td>2021</td> <td>2021</td> <td>ATLAS CROSS SPORT</td> </tr> </tbody> </table>	Country	Beginning Model Year	Ending Model Year	Vehicle	USA	2021	2021	ATLAS	USA	2021	2021	ATLAS CROSS SPORT
				Country	Beginning Model Year	Ending Model Year	Vehicle									
				USA	2021	2021	ATLAS									
				USA	2021	2021	ATLAS CROSS SPORT									
<p>The wheel bolt seat in the affected rims may not be machined to the correct depth dimension. If this condition is present, the incorrect dimension of the lug bolt holes may cause insufficient thread engagement of the wheel bolt to the wheel bearing hub. This may result in failure of the threads, which may lead to separation of the wheel from the vehicle and may lead to a crash without warning.</p>																
<p>To correct this defect, your authorized Volkswagen dealer will inspect all four wheels. Should an affected wheel be found, the wheel, lug bolts and wheel bearing will be replaced. The inspection will take about half an hour to complete. If parts are needed, repairs may take up to one day. This will all be performed for you free of charge. Please keep in mind that your dealer may need additional time for the preparation of the repair, as well as to accommodate their daily workshop schedule.</p>																
<p>When will the repair for Safety Recall 44Q9 be available?</p>	<p>Parts are available now and repairs have begun. Please contact your authorized Volkswagen dealer without delay to schedule this recall repair. To set up an appointment online, please visit www.vw.com/find-a-dealer.</p>															