CAMPAIGN LAUNCH STATUS

Notes



Customers were notified by mail on May 7th. SAJAR4BG1HA977182 / Cole European

SAJAL4FXXJCP30006 / Jaguar Darien SAJAJ4FX7LCP62811 / Jaguar Lakeside



SAFETY RECALL - H349 REAR SIDE MEMBER BRACKET MISSING SPOT WELDS AFFECTED MODELS 17, 18, 20MY Jaguar XE CURRENT VOLUME AFFECTED 3 USA The 3 affected vehicles previously had rear body repairs. The left and or right-side rear side members used in these repairs have RFPAIR been found to be missing some spot welds and need to be replaced under this recall with new bumper mounting parts with correct welding. Between 2.2 hrs and 3.9 hrs + DIDO REPAIR TIME CAMPAIGN LAUNCHED May 4th, 2021









