



94o6 Campaign Tip

Alternative Headlight Adjustment Cap

This notice is for:	✓ Dealer Principal ✓ Sales Manager	✓ Service Manager ✓ Parts Manager	✓ Warranty Administrator ✓ Technicians
Date	June 07, 2021		
Issue	Replacement headlight adjustment cap listed in ETKA is not available.		
Resolution	If the headlight adjustment cap is found damaged or missing during the 94o6 repair, the cap must be replaced. The supply of the part number listed in ETKA may be limited. If headlight adjustment cap, ETKA part number 8W0-941-041, is not available, cap part number 4E0-941-041 can be used as an alternative.		
Additional Information	<div style="border: 2px solid red; padding: 2px;">IMPORTANT REMINDER: VEHICLES AFFECTED BY SAFETY & COMPLIANCE RECALLS</div> <p>New Vehicles in Dealer Inventory: It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied. By law, dealers must correct, prior to delivery for sale or lease, any vehicle that fails to comply with an applicable Federal Motor Vehicle Safety Standard or that contains a defect relating to motor vehicle safety.</p> <p>Pre-Owned Vehicles in Dealer Inventory: Dealers should not deliver any pre-owned vehicles in their inventory which are involved in a safety or compliance recall until the defect has been remedied.</p>		

<END OF MESSAGE>