

# CAMPAIGN LAUNCH STATUS

## N598 RECALL 20-21MY DEFENDER - SMOKED REAR LAMPS



### SAFETY RECALL N598 REAR LAMPS MAY NOT OPERATE

AFFECTED MODELS	20-21MY Defender X model fitted with 'smoked' rear lamps
VOLUME AFFECTED	2785 USA 274 CAN
REPAIR	Should an intense light source shine directly on the rear of an affected vehicle at a certain angle, the stop, turn signal and/or tail lamp may experience an over-voltage event, and cease to function. Both rear lamp assemblies will be replaced to rectify this.
REPAIR TIME	c 2.0 hrs + DIDO
TARGET CAMPAIGN LAUNCH	Early Sept 2021
Notes	A new design of lamp has been approved and the supplier is commencing manufacture. Supply restrictions for semi conductors are increasing manufacturing lead times with recall launch quantities of lamps still to be determined

