

## CAMPAIGN LAUNCH STATUS

### N607 RECALL - N598 RECALL



SAFETY RECALL N607	
AFFECTED MODELS	20-21MY Discovery. Extension of the existing N400 recall VIN range to add a further set of vehicles up to new end VIN SALRA2BUXM2453142
VOLUME AFFECTED	1383 USA 83 CAN
REPAIR	The battery cable ground stud may be loose in the body and needs to be replaced. Insufficient ground contact may lead to intermittent operation of electrical equipment and unexpected engine shutdown. A new 6mm ground stud is to be installed above the existing location.
REPAIR TIME	0.2 hrs + Drive in/out
CAMPAIGN LAUNCH	Target by July 14 <sup>th</sup> 2021
Notes	Retailer notification bulletins NAS21.07.001 (CAN and NAS21.07.002(USA) were published July 1 <sup>st</sup> , 2021 Repair process will be the same as for N400 recall

SAFETY RECALL N598 REAR LAMPS MAY NOT OPERATE	
AFFECTED MODELS	20-21MY Defender X model fitted with 'smoked' rear lamps
VOLUME AFFECTED	2785 USA 274 CAN
REPAIR	Should an intense light source shine directly on the rear of an affected vehicle at a certain angle, the stop, turn signal and/or tail lamp may experience an over-voltage event, and cease to function. Both rear lamp assemblies will be replaced to rectify this.
REPAIR TIME	c 1.7 hrs + DIDO
TARGET CAMPAIGN LAUNCH	TBC
Notes	A new design of lamp has been approved and the supplier is commencing manufacture. Supply restrictions for semi conductors will increase lead times with recall launch quantities of lamps currently not expected in market before late August.