

CAMPAIGN LAUNCH STATUS

N623 SAFETY RECALL – RR SPORT & LR4 FUEL TANK LEAK



SAFETY RECALL N623 - FUEL LEAKING FROM TANK OUTLET PIPE FLANGE	
AFFECTED MODELS	10-13MY Range Rover Sport and 10-16MY LR4
VOLUME AFFECTED	111,746 USA
REPAIR	Customers have reported fuel odor, occasionally liquid fuel on the ground. Retailers have diagnosed cracked fuel outlet pipe flange which will be replaced with a part of revised design. Any vehicles diagnosed with this concern today should be repaired following current processes and parts. The recall will remain open.
REPAIR TIME	1.2 hrs + Drive in/out
CAMPAIGN LAUNCH TARGET	Parts availability now expected March 2022.
Notes	Retailer Notification bulletin NAS21.08.013 issued August 26 th 2021. Parts are being procured to support repair launch. Owner notification by October 8 th .2021. Claims must not be submitted until the recall repair is published.

