

TECHNICAL TOPICS

Powertrain



N623 Recall notes – Previous Modification

2010-2013MY Range Rover Sport
2010-2016 LR4

Customer Voice:

Customer will come in for the N623 Fuel tank recall

Technical Description:

JLR has been notified on some vehicles that have had a previous repair, (LTB00566NAS4 - Fuel Gauge Operation Inaccurate) where the wiring harness has been modified and no longer has Connector B shown in the picture to the right.

Status:

JLR had just validated the repair of the modified vehicles with the engineering team and are in the process of updating the campaign instructions. It will include some other service actions to accompany, SPO etc.

Refer to Recall N623

