

Subject:

[PROOF] Model 3 and Model Y Front Suspension Lateral Link Inspection



Tesla has decided to proactively recall certain Model 3 and Model Y vehicles to inspect the bolts that secure the lateral link in the front suspension. This recall applies to certain Model 3 vehicles built between January 2019 and April 2021 and certain Model Y vehicles built between March 2020 and June 2021. Our records indicate that your vehicle {VINXXXXXXXX}, may be affected by this recall.

On certain vehicles, the lateral link bolts may not have been secured to the correct specifications. This could cause the fasteners to loosen over time, which could cause the lateral link to separate from the sub-frame. If the fasteners become loose, you may detect abnormal noise from the front suspension. We are not aware of any crashes or injuries relating to this condition.

Please schedule a service appointment using the Tesla app by selecting 'Schedule Service' > 'Other' > 'Something Else' and entering the notes, "Open Recall Repair – Lateral Link inspection". At your appointment, Tesla Service will inspect your vehicle and perform any necessary repairs, free of charge.

Thank you for your support, and we apologize for the inconvenience.