



U.S. Department of Transportation  
**National Highway Traffic Safety  
Administration**

1200 New Jersey Avenue SE  
Washington, DC 20590

February 4, 2022

Ms. Shiela Albano  
Regulatory Compliance Lead  
Bridgestone Americas Tire Operations  
200 4th Ave S  
Nashville, TN 37201

NEF-107CL  
22T-002

**Subject:** Tire Inner Liner May Crack Causing Belt Separation

Dear Ms. Albano:

This letter serves to acknowledge Bridgestone Americas Tire Operations's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

**Makes/Models/Model Years:**

FIRESTONE/TRANSFORCE AT/LT275/70R18  
FIRESTONE/TRANSFORCE HT/LT275/70R18

**Mfr's Report Date:** February 1, 2022

**NHTSA Campaign Number:** 22T-002

**Components:**

TIRES:TREAD/BELT

**Potential Number of Units Affected:** 10,380

**Problem Description:**

Bridgestone Americas Tire Operations (Bridgestone) is recalling certain Firestone Transforce HT, size LT275/70R18 with DOT code VN15TH71821 and Transforce AT, size LT275/70R18 with DOT code VN15TR91821. The tires were manufactured with an incorrect inner liner compound, which could cause increased inner liner permeability or cracking, resulting in belt separation.

**Consequence:**

Belt separation could lead to loss of vehicle control, increasing the risk of a crash.

**Remedy:**

Bridgestone will notify owners and replace the affected tires with a comparable Bridgestone or Firestone brand tire, free of charge. Owner notification letters are expected to be mailed April 1, 2022. Owners may contact Bridgestone customer service at 1-800-847-3272.

**Notes:**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).

Please be reminded of the following requirements:




You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Bridgestone Americas Tire Operations's contact for this recall will be Choon Lee who may be reached by email at [choon.lee@dot.gov](mailto:choon.lee@dot.gov). We look forward to working with you.

Sincerely,



Alex Ansley  
Chief, Recall Management Division  
Office of Defects Investigation  
Enforcement