

February 17, 2022

Mr. John Kobylarz Safety Compliance Manager Jaguar Land Rover North America, LLC 100 Jaguar Land Rover Way Mahwah, NJ 07495

Subject: SRS Warning Light Malfunction

Dear Mr. Kobylarz:

This letter serves to acknowledge Jaguar Land Rover North America, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: LAND ROVER/RANGE ROVER EVOQUE/2020

Mfr's Report Date: February 15, 2022

NHTSA Campaign Number: 22V-080

Components:

AIR BAGS: AIR BAG/RESTRAINT CONTROL MODULE:SOFTWARE AIR BAGS:SRS MALFUNCTION WARNING LAMP/LIGHT

Potential Number of Units Affected: 18,824

Problem Description:

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2020 Range Rover Evoque vehicles. The supplemental restraint system (SRS) warning light software is programmed incorrectly, which may cause the warning light to malfunction and intermittently illuminate.

Consequence:

An SRS system warning light that falsely illuminates could prevent the detection of an actual air bag system failure, increasing the risk of injury in the event of a crash.

Remedy:

Dealers will update the restraints control module (RCM) software, free of charge. Owner notification letters are expected to be mailed April 14, 2022. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N664.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Image: Constraint of the second state of the second st

1200 New Jersey Avenue SE Washington, DC 20590

> NEF-107ES 22V-080

Please ensure the following requirements are met:

As required in Part 573.6, please amend the chronology to provide a summary of all warranty claims, field or service reports, and other information, with their dates of receipt. If claim count exceeds 10 claims, please provide the total number of claims, and a receipt date range for those claims.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Jaguar Land Rover North America, LLC's contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,

Lee And

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

