

U.S. Department of Transportation

National Highway Traffic Safety Administration

April 18, 2022

Mr. Greg Gunther Department Manager VCA Mercedes-Benz USA, LLC 13470 International Parkway Jacksonville, FL 32218

Subject: Unsecured Ground Connection Bolt

Dear Mr. Gunther:

This letter serves to acknowledge Mercedes-Benz USA, LLC's notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MERCEDES-BENZ/AMG GLE53/2021-2022

MERCEDES-BENZ/AMG GLE63/2021

MERCEDES-BENZ/AMG GLS63/2021

MERCEDES-BENZ/GLE450/2020-2022

MERCEDES-BENZ/GLE580/2020-2021

MERCEDES-BENZ/GLS450/2020-2022

MERCEDES-BENZ/GLS580/2020-2021

MERCEDES-BENZ/MAYBACH GLS600/2021

Mfr's Report Date: April 8, 2022

NHTSA Campaign Number: 22V-231

Components:

ELECTRICAL SYSTEM: WIRING: INTERIOR/UNDER DASH

Potential Number of Units Affected: 21.306

Problem Description:

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2020-2022 GLE450, GLS450, 2021-2022 AMG GLE53, 2020-2021 GLE580, GLS580, 2021 AMG GLE63, Maybach GLS600 and AMG GLS63 vehicles. A ground cable bolt for the 48V ground connection under the front passenger seat may not be secured properly, which can cause the electrical cable to overheat.

Consequence:

An overheated electrical cable can increase the risk of a fire.

Remedy:

Dealers will inspect and tighten the ground cable bolt, as necessary, free of charge. Owner notification letters are expected to be mailed June 7, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.



1200 New Jersey Avenue SE Washington, DC 20590

NEF-107ES

22V-231

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Mercedes-Benz USA, LLC's contact for this recall will be Emily C. Smith who may be reached by email at emily.c.smith@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

