

U.S. Department of Transportation

National Highway Traffic Safety Administration

June 1, 2022

Mr. Tony Sappington
Manager- Product Safety
McNeilus Truck & Manufacturing, Inc.
520 Hwy St E

NEF-107MR
22V-376

1200 New Jersey Avenue SE Washington, DC 20590

Dodge Čenter, MN 55927

Subject: Insufficient Clearance Between Tire and Fender

Dear Mr. Sappington:

This letter serves to acknowledge McNeilus Truck & Manufacturing, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years:

MCNEILUS/BRIDGEMASTER/2022

Mfr's Report Date: May 26, 2022

NHTSA Campaign Number: 22V-376

Components:

STRUCTURE:BODY

Potential Number of Units Affected: 8

Problem Description:

McNeilus Truck & Manufacturing, Inc. (McNeilus) is recalling certain 2022 Bridgemaster Mixer Trucks. Insufficient clearance between the tire and fender hardware could allow the tire to contact the fender hardware, possibly resulting in fender or fender tube detachment.

Consequence:

A detached fender or fender tube can create a road hazard, increasing the risk of a crash.

Remedy:

McNeilus will replace the fenders and fender tubes on the tag axle, free of charge. Owner notification letters are expected to be mailed on June 17, 2022. Owners may contact McNeilus's customer service at 1-888-868-7278.

Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



Please ensure the following requirements are met:

Per the requirements of 49 USC 30119, please provide the part number, name and description of the component or components involved in this recall. This information should be provided in an amended 573 in the "Involved Components" section.

AMENDED 573 REQUIRED.

Per the requirements of 573.6(c)(2)(iv), please provide the supplier name, contact information, address and country of origin (if known) for the tag axles. If your company manufactured the component itself, then please state so in 573.

AMENDED 573 REQUIRED.

Please be reminded of the following requirements:

You are required to submit a draft owner notification letter to this office no less than five days prior to mailing it to the customers. Also, copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

McNeilus Truck & Manufacturing, Inc.'s contact for this recall will be Michelle Rice who may be reached by email at michelle.rice@dot.gov. We look forward to working with you.

Sincerely,

Alex Ansley

Chief, Recall Management Division Office of Defects Investigation

Enforcement

