

July 19, 2022

Marie-Claude Simard Bombardier Recreational Products, Inc. 726 St-Joseph Street Valcourt, Quebec Canada J0E 2L0

Subject: Handlebar May Break

Dear Marie-Claude Simard:

This letter serves to acknowledge Bombardier Recreational Products, Inc.'s notification to the National Highway Traffic Safety Administration (NHTSA) of a safety recall which will be conducted pursuant to Federal law for the product(s) listed below. Please review the following information to ensure that it conforms to your records as this information is being made available to the public. If the information does not agree with your records, please contact us immediately to discuss your concerns.

Makes/Models/Model Years: CAN-AM/RYKER/2022

Mfr's Report Date: July 13, 2022

NHTSA Campaign Number: 22V-503

**Components:** STEERING: STEERING WHEEL/HANDLE BAR

Potential Number of Units Affected: 9,353

#### **Problem Description:**

Bombardier Recreational Products Inc. (BRP) is recalling certain 2022 Can-Am Ryker motorcycles. The handlebar stem bolt may break unexpectedly due to insufficient thread length.

#### **Consequence:**

A broken handlebar stem bolt can cause a sudden loss of steering control, increasing the risk of a crash.

#### **Remedy:**

Owners are advised to not ride their motorcycle until the remedy is complete. Dealers will clean the threads of the steering column and install a new steering stem bolt, free of charge. Owner notification letters are expected to be mailed July 27, 2022. Owners may contact BRP customer service at 1-888-272-9222. BRP's number for this recall is 2022-16.

#### Notes:

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.



1200 New Jersey Avenue SE Washington, DC 20590

NEF-107DM 22V-503

# Please ensure the following requirements are met:

Per the requirements of 573.6(c)(2)(iv), please provide the supplier name, contact information, address and country of origin (if known) for the handlebar stem bolt. If your company manufactured the component itself, then please state so in 573.

### AMENDED 573 REQUIRED.

Please amend the Part 573 report to include the owner advisory in the remedy section of the report.

## AMENDED 573 REQUIRED.

We have received BRP's proposed owner notification letter and it is approved for distribution.

Please be reminded of the following requirements:

Copies of all notices, bulletins, dealer notifications, and other communications that relate to this recall, including a copy of the final owner notification letter and any subsequent owner follow-up notification letter(s), are required to be submitted to this office no later than 5 days after they are originally sent (if they are sent to more than one manufacturer, distributor, dealer, or purchaser/owner).

Please be reminded that under 49 U.S.C. § 30112(a)(3), it is illegal for a manufacturer, to sell, offer for sale, import, or introduce or deliver into interstate commerce, a motor vehicle or item of motor vehicle equipment that contains a safety defect once the manufacturer has notified NHTSA about that safety defect. This prohibition does not apply once the motor vehicle or motor vehicle equipment has been remedied according to the manufacturer's instructions.

As stated in Part 573.7, submission of the first of eight consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. Therefore, the first quarterly report will be due on, or before, 30 days after the close of the calendar quarter.

Bombardier Recreational Products, Inc.'s contact for this recall will be DeMara Magruder who may be reached by email at demara.magruder@dot.gov. We look forward to working with you.

Sincerely,

Alae Andy

Alex Ansley Chief, Recall Management Division Office of Defects Investigation Enforcement

