## **Recall Quarterly Report**

22V-681

Manufacturer Name : Daimler Trucks North America, LLC NHTSA Recall No. / MFR Recall No. : 22V-681 /FL952 Recall Subject : Improperly Installed Steering Shaft Bolt Owner Notification Beginning Date : OCT 11, 2022 Owner Notification End Date: OCT 11, 2022



Report #	Submission Date	Report Quarter	Recall Population	Total Remedied	Total Unreachable	Total Removed
5	JAN 23, 2024	2023-4	200	160	0	0
4	OCT 20, 2023	2023-3	200	145	0	0
3	JUL 18, 2023	2023-2	200	127	0	0
2	APR 24, 2023	2023-1	200	102	0	0
1	JAN 28, 2023	2022-4	200	65	0	0

This Document Last Updated : JAN 25, 2024

## **Definitions :**

Report Quarter : The quarter the manufacturer is reporting recall completion figures (e.g. 2012-3 means the 3<sup>rd</sup> quarter of 2012). Recall Population : The total number of products recalled by the manufacturer.

Total Remedied : The total number of products either remedied, inspected without needing remedy, or returned to inventory. Total Unreachable : Products deemed unreachable as owner notifications were unable to be delivered.

Total Removed : Products that have been scrapped, stolen, or exported.