# Part 573 Safety Recall Report

Manufacturer Name :Power Solutions International, Inc.Submission Date :OCT 12, 2022NHTSA Recall No. :22E-084Manufacturer Recall No. :NR

## Manufacturer Information :

Manufacturer Name : Power Solutions International, Inc. Address : 201 Mittel Drive Wood Dale IL 60191 Company phone : 350-9400

## **Population :**

Number of potentially involved : 8,046 Estimated percentage with defect : 100 %

云 🔨 🔂

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

22E-084

### **Equipment Information :**

|                           | Power Solutions Internati  |
|---------------------------|--|
| Model :                   | 8.8L OBD HD Engines  |
| Part No. :                | Multiple   |
| Size :                    | NR   |
| Function :                | NR   |
| Descriptive Information : | The suspect PSI 8.8L Gasoline or Gen II LPG products which use the MT88 controller in the school bus chassis and/or school bus chassis CAN network architecture have been identified by the vehicle OEM and submitted in their respective OEM's 573 reports. |
| Production Dates :        | JAN 17, 2019 - MAR 01, 2022  |

### **Description of Defect :**

| Description of the Defect :      | With the vehicle in motion, the engine control module (ECM) may set fault code<br>SPN 629 FMI 12 resulting in an engine shut down without warning. The<br>calibration installed on the ECM is designed to shut the engine down in<br>response to fault code SPN 629 FMI 12.                 |
|----------------------------------|---|
|                                  | The root cause of the generation of fault code SPN 629 FMI 12 has not been determined. PSI has concluded that the fault code is not generated solely by engine and ECM interaction, but PSI has not been able to fully investigate other vehicle system interactions outside of its control |
| FMVSS 1 :                        | NR  |
| FMVSS 2 :                        | NR  |
| Description of the Safety Risk : | In certain conditions, an unintended shut down without warning may result<br>in an increased risk of a crash.   |
| Description of the Cause :       | NR  |
|                                  |   |

The information contained in this report was submitted pursuant to 49 CFR §573

## Part 573 Safety Recall Report

Page 2

Identification of Any Warning NR that can Occur :

#### **Involved Components :**

Component Name : MT88 ECM

Component Description : Engine Control Module

Component Part Number : 32502960

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : BorgWarner (Formally Delphi)

Address : Avenida de los Encinos 1050

- Parque Industrial Villa Florida Reynosa Foreign States 88718
- Country: Mexico

#### **Chronology**:

NR

#### **Description of Remedy :**

Description of Remedy Program :OEM's have launched or are int he process of executing a recall on their<br/>vehicles. PSI will not be handling any quarterly reporting.How Remedy Component Differs<br/>from Recalled Component :NRIdentify How/When Recall Condition<br/>was Corrected in Production :NR

#### **Recall Schedule :**

| Description of Recall Schedule :   | OEM's have launched or are int he process of executing a recall on their |
|------------------------------------|--|
|                                    | vehicles. PSI will not be handling any quarterly reporting.              |
| Planned Dealer Notification Date : | NR - NR  |

The information contained in this report was submitted pursuant to 49 CFR §573

## Part 573 Safety Recall Report

22E-084

Page 3

Planned Owner Notification Date : NR - NR

#### **Purchaser Information :**

The following manufacturers purchased this defective/noncompliant equipment for possible use or installation in new motor vehicles or new items of motor vehicle equipment:

Name :Navistar, Inc.Address :2701 Navistar Drive<br/>Lisle IL 60532Country :USCompany Phone :8004487825Name :Daimler Trucks North America<br/>Address :Address :4747 N. Channel Ave<br/>Portland OR 97217Country :USCompany Phone :8007458000

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573