

# Part 573 Safety Recall Report

## 22V-005

**Manufacturer Name :** Lakota Corporation

**Submission Date :** DEC 16, 2022

**NHTSA Recall No. :** 22V-005

**Manufacturer Recall No. :** NR



### Manufacturer Information :

**Manufacturer Name :** Lakota Corporation

**Address :** PO Box 219

4 Stoutco Drive Bristol IN 46507

**Company phone :** 574-848-1636

### Population :

**Number of potentially involved :** 68

**Estimated percentage with defect :** 100 %

### Vehicle Information :

**Vehicle 1 :** 2021-2022 Lakota Bighorn & Charger & Livestock

**Vehicle Type :** TRAILERS

**Body Style :**

**Power Train :** NR

**Descriptive Information :** still determining what trailers contain the recalled tires. removing trailers from the list that were a different plant number, total number of trailers 70. 68 US trailers and 2 in Canada.

**Production Dates :** JUN 01, 2020 - DEC 31, 2020

**VIN Range 1 : Begin :**

NR

**End :** NR

Not sequential

### Description of Defect :

**Description of the Defect :** Sailun tires, tread belt separation or tread delamination

**FMVSS 1 :** NR

**FMVSS 2 :** NR

**Description of the Safety Risk :** risk of crash

**Description of the Cause :** defect with a steel belt package design

**Identification of Any Warning that can Occur :** NR

### Involved Components :

Component Name 1 : Sailun Tire

Component Description : 16" tire DOT code 2020-4120

Component Part Number : 235/85R16 G

## Supplier Identification :

### Component Manufacturer

Name : Sailun Tire Americas

Address : NR

NR

Country : United States

## Chronology :

Tredit Tire and Wheel sent Lakota trailers a letter indicating Sailun Tire Americas has issued a recall, 21T-018. Letter was received from Tredit Tire January 3, 2022. Lakota is the end manufacture and ultimately responsible to issue the recall. It was immediately decided that a recall would be issued to dealers and owners. Reports were ran to determine quantity and specific trailers containing the tires under the Sailun recall.

## Description of Remedy :

Description of Remedy Program : The defect is associated with a steel belt package design change that could contribute to a tread belt separation or tread delamination

How Remedy Component Differs from Recalled Component : the new ties will not have the steel belt package defect. tires will be replaced by Sailun at no charge to the customers.

Identify How/When Recall Condition was Corrected in Production : I will have to reach out to Sailun to find out.

## Recall Schedule :

Description of Recall Schedule : letters will be issues to dealers and retail owners.

Planned Dealer Notification Date : FEB 11, 2022 - FEB 11, 2022

Planned Owner Notification Date : FEB 18, 2022 - FEB 18, 2022

\* NR - Not Reported