

# Part 573 Safety Recall Report

## 22V-021

**Manufacturer Name :** Hino Motors Sales U.S.A., Inc.

**Submission Date :** FEB 23, 2022

**NHTSA Recall No. :** 22V-021

**Manufacturer Recall No. :** AANTO



### Manufacturer Information :

Manufacturer Name : Hino Motors Sales U.S.A., Inc.

Address : 45501 Twelve Mile Road

Novi MI 48377

Company phone : 248-699-9300

### Population :

Number of potentially involved : 1

Estimated percentage with defect : 100 %

### Vehicle Information :

Vehicle 1 : 2021-2021 HINO NJ8A

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : ALL

Power Train : DIESEL

**Descriptive Information :** Hino identified a single subject vehicle with a replacement air brake hose assembly in which the end fittings of that air brake hose lacked a manufacturer designation. The single replacement air brake hose assembly identified did not contain a manufacturer designation pursuant to 49 C.F.R. 571.106 S7.2.2(b) and 49 C.F.R. 571.106 S7.2.3.1. The single replacement air brake hose assembly was distributed through the Service Parts Network.

**Production Dates :** JAN 31, 2020 - JAN 31, 2020

VIN Range 1 : Begin : 5PVNJ8AV6M5T50057 End : 5PVNJ8AV6M5T50057

☐ Not sequential

VIN Range 2 : Begin : 5PVNJ8AV6M5T50057 End : 5PVNJ8AV6M5T50057

☐ Not sequential

### Description of Noncompliance :

**Description of the Noncompliance :** The single replacement air brake hose assembly end fitting did not contain the manufacturer designation requirement of FMVSS No.106 S7.2.2 (b) and FMVSS No.106 S7.2.3.1.

FMVSS 1 : 106 - Brake hoses

FMVSS 2 : NR

**Description of the Safety Risk :** Hino identified a single vehicle with an air brake hose end fitting that did not contain the manufacturer designation pursuant to FMVSS No.106 S7.2.2 (b) and FMVSS No.106 S7.2.3.1. Hino has determined the single subject air brake hose end fitting, although missing the manufacturer's designation, met all of the performance requirements of FMVSS 106. The single subject air brake hose end fitting may not be traceable should there be a performance concern, increasing the risk of a crash, injury, or fire.

Description of the Cause : A change in the supplier that provided the replacement part air brake hose assembly resulted in the missing manufacturer designation on a single air brake hose assembly installed as a replacement on a single vehicle.

Identification of Any Warning that can Occur : N/A

### Involved Components :

Component Name 1 : HOSE SUB-ASSY, AIR

Component Description : AIR BRAKE HOSE

Component Part Number : S4703-E0W40

### Supplier Identification :

#### Component Manufacturer

Name : MEIJI FLOW SYSTEMS CO., LTD.

Address : Kasei-Machi 31-7, Nobusawa

Kanagawa Prefecture Ashigarakami-Gun Foreign States 256-0026

Country : Japan

### Chronology :

September 2021 ~ December 2021

During the development of the new model vehicle, it was discovered that a particular replacement air brake hose assembly did not have the manufacturer designation on the air brake hose end fittings. Investigation revealed that a replacement air brake hose assembly was sold via a Hino dealer and installed in a single vehicle. No other affected vehicles were identified.

January 17, 2022

Based on the investigation above, Hino confirmed that the subject air brake hose assembly meets all requirements of FMVSS 106 with the exception of the manufacturer's designation specifically required for assemblies under FMVSS 106 S7.2.3. Therefore, Hino has determined to perform a recall on the air brake hose assemblies which were distributed through the service parts network.

### Description of Remedy :

Description of Remedy Program : For the subject affected vehicle, the dealer directly contacted the owner and replaced the subject hose free of charge on February 8, 2022.

How Remedy Component Differs from Recalled Component : The remedy air brake hose assembly has the manufacturer designation on the end fittings.

Identify How/When Recall Condition was Corrected in Production : N/A

### Recall Schedule :

Description of Recall Schedule : On or before February 8, 2022, the single brake hose assembly for this single subject vehicle was repaired and replaced by the dealer without charge to the owner. Notification of the noncompliance to the dealer and owner was completed on or before February 8, 2022.

Planned Dealer Notification Date : FEB 08, 2022 - FEB 08, 2022

Planned Owner Notification Date : FEB 08, 2022 - FEB 08, 2022

\* NR - Not Reported