OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 22V-117

**Manufacturer Name:** Keystone RV Company

**Submission Date:** MAR 04, 2022 **NHTSA Recall No.:** 22V-117



### **Manufacturer Information:**

Manufacturer Recall No.: 22-424

Manufacturer Name: Keystone RV Company

Address: PO Box 2000

2642 Hackberry Drive Goshen IN

46527

Company phone: 574-535-2100

# **Population:**

Number of potentially involved : 95 Estimated percentage with defect : 100 %

### **Vehicle Information:**

Vehicle 1: 2022-2022 Crossroads Sunset 330SI

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: 330SI floor plans

Production Dates: NOV 30, 2021 - FEB 10, 2022

VIN Range 1: Begin: 4YDTSSR2XN5351450 End: 4YDTSSR2XN5352159 ✓ Not sequential

### **Description of Defect:**

Description of the Defect: It has been decided that the vehicles in the recall population have a circuit that

is not properly protected by a ground-fault circuit interrupter (GFCI).

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The outside receptacle is not properly protected by a GFCI and is not installed

according to code under NFPA 70, which could lead to an increased risk of

personal injury.

Description of the Cause: The outside receptacle is not ground fault protected.

Identification of Any Warning NR

that can Occur:

## **Involved Components:**

# **Part 573 Safety Recall Report**

22V-117

Page 2

Component Name 1: Recept

Component Description: Recept - Blank - Junction - SC014-S3 - P & S

Component Part Number: 107256

### **Supplier Identification:**

### **Component Manufacturer**

Name: NR Address: NR

NR

Country: NR

### **Chronology:**

2/16/2022 – Report was made during a routine audit that the outside receptacle was not GFCI protected. 2/17/2022 – Investigation opened. All affected Sunsets were put on hold and circuits were inspected. Range

and scope to be determined.

2/25/2022 - Investigation concluded and scope completed.

### **Description of Remedy:**

Description of Remedy Program: The remedy is to wire the circuit properly so that the outside receptacle is

properly protected. Manufacturer Reimbursement Plan on file as of

 $10/07/2020. \ \ General\ reimbursement\ plan\ to\ be\ updated\ every\ two\ years.$ 

New vehicles are covered under warranty.

How Remedy Component Differs The outside receptacle will be properly protected once the circuit is wired

from Recalled Component: properly.

Identify How/When Recall Condition Units were quarantined, inspected then repaired as indicated by

was Corrected in Production: inspection.

#### **Recall Schedule:**

Description of Recall Schedule: Keystone will notify the dealers and owners of the recreational vehicles

by letter. A final copy of the owner letter will be provided to NHTSA,

along with the dealer repair procedures.

Planned Dealer Notification Date: APR 25, 2022 - APR 25, 2022 Planned Owner Notification Date: APR 25, 2022 - APR 25, 2022

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report	22V-117	Page 3
* NR - Not Reported		
The information contained in this report was submitte	d nursuant to 40 CED SE72	