The information contained in this report was submitted pursuant to 49 CFR §573

## **Part 573 Safety Recall Report**

Manufacturer Name : Winnebago Towable

Submission Date : MAY 16, 2022

NHTSA Recall No.: 22V-157

Manufacturer Recall No.: NR **Manufacturer Information : Population**: Manufacturer Name : Winnebago Towable Number of potentially involved : 1,638 Address: 201 14th Street Estimated percentage with defect: 1% Middlebury IN 46540 Company phone: 825-5250 **Vehicle Information :** Vehicle 1: 2022-2022 Winnebago TBD Vehicle Type : **Body Style :** Power Train : NR Descriptive Information : Based on Norco delivery dates of affected frames in recall 22E-003 Production Dates : SEP 09, 2021 - OCT 31, 2021 Not sequential VIN Range 1 : Begin : NR End: NR **Description of Defect :** 

Description of the Defect : On the frames used to build these RVs, some couplers where not fully welded / welds were missing **Reference recall E22-003** FMVSS 1: NR FMVSS 2: NR Description of the Safety Risk : The coupler welds could fail and may cause trailer/tow vehicle separation resulting in a crash which could result in serious injury or death. Description of the Cause : NR Identification of Any Warning NR that can Occur:

**Involved Components :** 

🔂 🔆 🗥 🕁



## 22V-157

# Part 573 Safety Recall Report

22V-157

Component Name 1 : Coupler Component Description : NR

Component Part Number: CA-5400-0 and CA-5400-B

### **Supplier Identification :**

### **Component Manufacturer**

Name :Pacific Trailer Products, IncAddress :19215 SE 34th StreetCamas Washington 98607Country :United States

### **Chronology** :

March 8, 2022 Norco (frame mfg) sent notice of recall E22-003 March 8 2022 to present Recall group has meetings and researching affected product March 15, 2022 - 573 notice submitted to portal

#### **Description of Remedy :**

Description of Remedy Program :	Winnebago service centers will inspect and if needed replace coupler . Reimbursement for recalls go through the same as a warranty claim.
How Remedy Component Differs from Recalled Component :	The recall coupler will have spot welds, remedy component will have full beads of weld
Identify How/When Recall Condition was Corrected in Production :	couplers were inspected for full weld

#### **Recall Schedule :**

Description of Recall Schedule :	TBD
Planned Dealer Notification Date :	JUN 03, 2022 - JUN 03, 2022
Planned Owner Notification Date :	APR 20, 2022 - JUN 03, 2022

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573