OMB Control No.: 2127-0004

Part 573 Safety Recall Report

22V-201

Manufacturer Name: Lance Camper Manufacturing. Corp.

Submission Date: MAY 04, 2022 **NHTSA Recall No.:** 22V-201

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Lance Camper Manufacturing. Corp.

Address: 43120 Venture Street

Lancaster CA 93535

Company phone: 661-949-3322

Population:

Number of potentially involved: 18 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2022-2022 Lance 1685, 1985, 1995, 2185, 2445

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: discovered on the line on new 2022 units with the Truma water heater option.

all units built within the dates are effected

18 units effected

Production Dates: OCT 05, 2021 - FEB 26, 2022

VIN Range 1: Begin: 56YTT2420NL332523 End: 56YTT2127NL333141 ✓ Not sequential

Description of Defect:

Description of the Defect: Truma water heater, DATA CABLE IS ROUTED THROUGH THE COLD WATER

INLET IN THE REAR OF THE WATER HEATER AND COULD REST AGAINST

BURNER BOX

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: DATA CABLE SHORT POSSIBLE FIRE

Description of the Cause: DATA CABLE MELTED FROM BURNER BOX

Identification of Any Warning WATER HEATER CONTROL PANEL AND WATER HEATER INOPERERTIBLE.

that can Occur:

Involved Components:

Component Name 1: Gas connector elbow kit

Component Description: kit includes hole plug, rubber insulator, zip tie and elbow if needed

Component Part Number: 77000-37500

Supplier Identification:

Component Manufacturer

Name: NR Address: NR

NR

Country: NR

Chronology:

IDENTIFIED ON THE PRODUCTION LINE THAT THE DATA CABLE WAS NOT BEING INSTALLED PER THE MANUFACTURER SPECIFACATIONS.

Description of Remedy:

Description of Remedy Program: REROUTE THE DATA CABLE FROM THE COLD WATER INLET AND

REROUTE PER MANUFACTURER SPECIFACATIONS.

LANCE WILL REIMBURSE DEALER THROUGH A WARRANTY CLAIM.

NOTE:Customers who have had this remedy completed before this recall are eligible for reimbursement, contact Lance customer service (661)

949-3322

How Remedy Component Differs INSTALLATION ERROR.

from Recalled Component:

Identify How/When Recall Condition ROUTED THE DATA CABLE PER THE MANUFACTURER SPECIFICATIONS

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: MAIL OUT DEALER AND CUSTOMER LETTERS

Planned Dealer Notification Date : MAY 27, 2022 - JUN 30, 2022 Planned Owner Notification Date : MAY 27, 2022 - JUN 30, 2022

Part 573 Safety Recall Report	22V-201	Page 3
* NR - Not Reported		
The information contained in this report was submitted	pursuant to 49 CFR §573	