

Part 573 Safety Recall Report

22V-391

Manufacturer Name : Elgin Sweeper Company, Inc.

Submission Date : JUN 01, 2022

NHTSA Recall No. : 22V-391

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Elgin Sweeper Company, Inc.

Address : 1300 West Bartlett Road

Elgin IL 60120-7259

Company phone : 847-741-5370

Population :

Number of potentially involved : NR

Estimated percentage with defect : NR

Vehicle Information :

Vehicle 1 : 2018-2022 Elgin Sweeper RegenX

Vehicle Type : LOW VOLUME VEHICLES

Body Style : OTHER

Power Train : DIESEL

Descriptive Information : All units of this model potentially have this safety defect. This defect is limited to this product model.

Production Dates : DEC 26, 2018 - MAY 31, 2022

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : The fan assembly mounting bolts may have been improperly torqued.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : The fan assembly could become detached and fall from the machine. This can cause a vehicle crash without prior warning, increasing risk of property damage, personal injury, or death.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition NR
was Corrected in Production :

Recall Schedule :

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported