

# Part 573 Safety Recall Report

# 22V-525

**Manufacturer Name :** Jaguar Land Rover North America, LLC**Submission Date :** JUL 21, 2022**NHTSA Recall No. :** 22V-525**Manufacturer Recall No. :** H404**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 5,326

Address : 100 Jaguar Land Rover Way

Estimated percentage with defect : 1 %

Mahwah NJ 07495

Company phone : 8188500

**Vehicle Information :**

Vehicle 1 : 2021-2022 JAGUAR F-PACE

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : NR

**Descriptive Information :** Jaguar Land Rover is conducting a voluntary safety recall campaign involving certain 2021 & 2022, Model Year Jaguar F-PACE vehicles built at the Solihull Vehicle Assembly Plant from October 23, 2020 - April 27, 2022. Approximately 5326 vehicles in the United States and Federalized Territories. The basis of the recall population was derived from Jaguar Land Rover data where the VIN range for vehicles affected was determined by specific model type and production date where the lamp design was introduced at 21 Model Year.

Production Dates : OCT 23, 2020 - APR 27, 2022

VIN Range 1 : Begin : SADCJ2EX6MA661872 End : SADCJ2EX1NA697664  Not sequential**Description of Defect :**

**Description of the Defect :** A concern has been identified on certain 2021 & 2022 Model Year Jaguar F-PACE vehicles where the incorrect specification tailgate mounted rear lamps may have been installed resulting in part of the rear indicator not being illuminated correctly. In a failed state, the rear lamps do not conform to the requirements of FMVSS 108.

FMVSS 1 : NR

FMVSS 2 : NR

**Description of the Safety Risk :** Incorrect illumination of the rear indicators may result in the indicator not being seen from the rear of the vehicle and an increased risk of a crash.

**Description of the Cause :** NR

**Identification of Any Warning that can Occur :** NR

## Involved Components :

Component Name 1 : Tailgate Mounted Rear Lamp

Component Description : Tailgate Mounted Rear Lamp

Component Part Number : T4A44678

Component Name 2 : Tailgate Mounted Rear Lamp

Component Description : Tailgate Mounted Rear Lamp

Component Part Number : T4A44679

Component Name 3 : Tailgate Mounted Rear Lamp

Component Description : Tailgate Mounted Rear Lamp

Component Part Number : T4A44680

Component Name 4 : Tailgate Mounted Rear Lamp

Component Description : Tailgate Mounted Rear Lamp

Component Part Number : T4A44681

## Supplier Identification :

### Component Manufacturer

Name : VARROC LIGHTING SYSTEMS

Address : Suvorovova 195

Senov u Noveha Jicina Foreign States 742 42

Country : Czech Republic

## Chronology :

See File "Recall H404 Chronology".

## Description of Remedy :

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to an approved Jaguar Land Rover repairer. The technician will inspect the rear lamp operation and where an incorrect specification tail lamp has been installed, it will be replaced with a lamp of the correct specifications.

There will be no charge to the owners for this repair.

The affected vehicles will be covered under Land Rover's new vehicle warranty program. Therefore, reimbursement for pre-notice remedies are not necessary because the affected vehicles are still under warranty.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

## Recall Schedule :

Description of Recall Schedule : Distribution of owner notification letters will occur on or before September 16, 2022. Notifications to dealers will occur on August 4, 2022.

Planned Dealer Notification Date : AUG 04, 2022 - AUG 04, 2022

Planned Owner Notification Date : SEP 16, 2022 - SEP 16, 2022

\* NR - Not Reported