OMB Control No.: 2127-0004

Part 573 Safety Recall Report

22V-568

Manufacturer Name: Tiffin Motorhomes, Inc.

Submission Date: AUG 18, 2022 NHTSA Recall No.: 22V-568 Manufacturer Recall No.: WAY-103



Manufacturer Information:

Manufacturer Name: Tiffin Motorhomes, Inc.

Address: 105 2nd Street NW

PO Box 596 Red Bay AL 35582

Company phone: 999

Population:

Number of potentially involved: 10 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2022-2022 Tiffin Midas

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : GAS

Descriptive Information: Center marker light left off on all units produced since the beginning of Midas

production.

Production Dates: DEC 21, 2021 - JUL 27, 2022

VIN Range 1 : Begin : NR End : NR Not sequential

Description of Noncompliance:

Description of the Center marker light left off due to back-up camera was put in it's place in the

Noncompliance: rear cap.

FMVSS 1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2: NR

Description of the Safety Risk: It is a marker light used for others to see coach. If not there, the visibility of

coach to others could be impaired and cause increase risk of crash.

Description of the Cause: The hole in the rear cap that was supposed to house the center marker light

was used instead for back-up camera. Error in production.

Identification of Any Warning None.

that can Occur:

Involved Components:

Component Name 1: Marker Light

Component Description: Center Marker Light

Component Part Number: 5127680 (Tiffin part #)

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

7/27/22 Safety Committee was advised of non-compliance due to center marker light had been left off. Decision was made to submit 573 for recall. No vote needed. There have been no claims or reports of problems to date.

Description of Remedy:

Description of Remedy Program: Tiffin will notify the affected population and have the camera moved down

and center marker light inserted. This install will be at no charge to owner. If the owner has paid for any repairs related to this defect, they can submit

their invoice to Tiffin Motorhomes for reimbursement.

How Remedy Component Differs The remedied unit will have the center marker light, whereas the recalled

from Recalled Component: unit will not.

Identify How/When Recall Condition Engineering Change Modification dated 7/28/2022 states "Move camera

was Corrected in Production: down and add center marker light".

Recall Schedule:

Description of Recall Schedule: Owners and dealers will be notified of the recall and the Installation of

the center marker light will be performed at no charge to the customer.

Planned Dealer Notification Date: SEP 30, 2022 - SEP 30, 2022 Planned Owner Notification Date: SEP 30, 2022 - SEP 30, 2022

Part 573 Safety Recall Report	22V-568	Page 3
* NR - Not Reported		
The information contained in this report was submitted	ed pursuant to 49 CFR §573	