#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 22V-824

**Manufacturer Name:** Quality Trailers Ohio, Inc.

Submission Date: NOV 02, 2022 NHTSA Recall No.: 22V-824

Manufacturer Recall No.: NR



#### **Manufacturer Information:**

Manufacturer Name: Quality Trailers Ohio, Inc.

Address: 1664 SALEM PARKWAY WEST

**SALEM OH 44460** 

Company phone: 999

## **Population:**

Number of potentially involved: 534 Estimated percentage with defect: NR

#### **Vehicle Information:**

Vehicle 1: 2022-2022 Quality A, AW, B, DH

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information : Product Recall for the 2(5/16)" A-Frame Coupler received. There are 3 welds on the

underside of the coupler that may have only been tack welded instead of a solid weld. Any trailer with a weld on A-Frame 2(5/16)" Coupler may possibly be affected -

although no defects were found in our product inventory.

Models Affected: AW (Wood Deck Car Hauler), A (Diamond Deck Car Hauler), Tandem B (Tandem Axle Landscape Trailer), and Economy Series DH (Wood Deck Equipment

Trailer).

Possible Affected GVWR: 7,000, 8500, 9,990

Possible Affected Lengths: 12', 14', 16', 18', 20', 22', 24'

Production Dates: DEC 06, 2021 - MAR 11, 2022

#### **Description of Defect:**

Description of the Defect: There are 3 welds on the underside of the coupler that may have only been tack

welded instead of a solid weld (incomplete weld on the bottom side of

coupler)..

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: The welds on the bottom side of the coupler could break causing possible

disconnect with tow vehicle increasing the risk of a crash.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

### **Involved Components:**

Component Name 1: A-Frame 2(5/16)" Coupler

Component Description: Weld On A-Frame 2(5/16)" Coupler

Component Part Number: CA-5400-0

## **Supplier Identification:**

## **Component Manufacturer**

Name: Pacific Trailer Products Inc.

Address: 19215 SE 34th St

Suite 106 #345 Camas Washington 98607

**Country: United States** 

## **Chronology:**

Received Product on 12/6/21 - Received Product Recall via mail early March 2022 - Checked Inventory found no defective couplers, but e-mailed our dealers with information on the recall on 3/11/22.

#### **Description of Remedy:**

Description of Remedy Program: NR

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: NR

Planned Dealer Notification Date : NR - NR Planned Owner Notification Date : NR - NR

<sup>\*</sup> NR - Not Reported