

Part 573 Safety Recall Report

22V-912

Manufacturer Name : Kawasaki Motors Corp., U.S.A.

Submission Date : DEC 09, 2022

NHTSA Recall No. : 22V-912

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Kawasaki Motors Corp., U.S.A.

Address : PO Box 25252
Santa Ana CA 92799-5252

Company phone : 949-770-0400

Population :

Number of potentially involved : 3,172

Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1 : 2015-2023 Kawasaki Motors, Ltd. ZX1000N/X, ZX1002J, ZX1002A/B/D/R, ZR1000K/L

Vehicle Type : MOTORCYCLES

Body Style : OTHER

Power Train : GAS

Descriptive Information : The affected vehicles containing the problem are certain 2015-2023 ZX1000N/X, ZX1002J (Kawasaki/Ninja H2/H2 Carbon/830), ZX1002A/B/D/R (Kawasaki/Ninja H2 SX/SX SE/1,166), ZR1000K/L (Kawasaki/Z H2/H2 SE/1,176) models. The recall population was determined by the beginning and ending production dates for the models affected.

Production Dates : DEC 01, 2014 - SEP 27, 2022

VIN Range 1 : Begin : JKAZXCN10FA000065 End : JKBZXVJ17NA004304

☐ Not sequential

VIN Range 2 : Begin : JKBZXVB10JA000006 End : JKBZXVD17MA005141

☐ Not sequential

VIN Range 3 : Begin : JKAZRCL11MA000005 End : JKAZRCK16PA015234

☐ Not sequential

Description of Defect :

Description of the Defect : The plunger in the camshaft-chain tensioner can lock up during usage due to deterioration of internal parts. Continuous use in this condition can result in loss of engine power during use.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : There is a risk that the engine could stop during operation due to the camshaft timing deviation.

Description of the Cause : Deterioration of internal parts in the tensioner during usage.

Identification of Any Warning that can Occur : An abnormal noise will be generated around the right side of the engine.

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :**Component Manufacturer**

Name : Kawasaki Motors Ltd.

Address : 1-1, Kawasaki-cho
Akashi Foreign States 673-8666

Country : Japan

Chronology :

NR

Description of Remedy :

Description of Remedy Program : NR

How Remedy Component Differs NR
from Recalled Component :Identify How/When Recall Condition NR
was Corrected in Production :**Recall Schedule :**

Description of Recall Schedule : NR

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : NR - NR

* NR - Not Reported