

Part 573 Safety Recall Report

22V-952

Manufacturer Name : Lion Electric Company

Submission Date : DEC 23, 2022

NHTSA Recall No. : 22V-952

Manufacturer Recall No. : NR



Manufacturer Information :

Population :

Manufacturer Name : Lion Electric Company

Number of potentially involved : 13

Address : 921, chemin de la Riviere-du-Nord
Saint-Jerome, Quebec, Canada 00 J7Y
5G2

Estimated percentage with defect : 50 %

Company phone : 1-855-546-6706

Vehicle Information :

Vehicle 1 : 2020-2022 Lion Lion6, Lion8

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : 2-DOOR

Power Train : HYBRID ELECTRIC

Descriptive Information : We have determined the number of impacted vehicles with our database, and these are all Lion6 and Lion 8 vehicles produced and sold in the United States. We have corrected the defect on the production line, since November 3rd

Production Dates : JAN 01, 2020 - NOV 03, 2022

VIN Range 1 : Begin : NR

End : NR

☐ Not sequential

Description of Defect :

Description of the Defect : During the assembly of the axle, we found that the fasteners that hold the adjusting rings were not consistently tightened to the required torque on the passenger side, which could lead to the introduction of play into the assembly. These missed adjustment steps could cause premature wear of the suspension and differential components.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In this situation, the right-side suspension could fail and separate from the truck frame, resulting in a loss of control of the rear of the vehicle.

The probability of the identified failure is rated as "unlikely". However, the impacts of such a failure could represent a human safety issue and would likely cause an accident.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

Quality inspectors issued an alert regarding 2 trucks on the production line with the quick fit nut not being tightened enough.

Service department checked the 8 Lion6's that were in inventory and 4 of them needed the nut on the passenger side tightened.

Description of Remedy :

Description of Remedy Program : All costs will be paid by the Lion Electric Company, we will send teams to do the repairs at the customers site.

How Remedy Component Differs NR
from Recalled Component :

Identify How/When Recall Condition was Corrected in Production : We have corrected the defect on the production line, since November 3rd

Recall Schedule :

Description of Recall Schedule : We don't have any dealer to notify.

Planned Dealer Notification Date : NR - NR

Planned Owner Notification Date : JAN 16, 2023 - JAN 27, 2023

* NR - Not Reported