



---

## **New Safety Recall Advanced Communication – Z51**

FCA US LLC (FCA US) has announced an equipment safety recall on certain Mopar Taillamps part numbers (PN's): **68421132AD** and **68421133AD**

### **REASON FOR THIS SAFETY RECALL**

Customers may have purchased the above Taillamps PN's which may have been built with a damaged taillamp/side marker and may have a nonfunctional taillamp/side marker. Vehicles with inoperative taillamp/side marker may result in an approaching vehicle being unaware of the position and dimensions of the vehicle and can cause a crash without prior warning.

The condition described above does not comply with Federal Motor Vehicle Safety Standard (FMVSS) No. 108 requires each vehicle to be equipped with at least two red steady burning taillamp-side markers.

### **SERVICE ACTION**

FCA US will conduct a voluntary safety recall on all affected parts to replace the tail lamps assemblies. Dealers will be notified of the launch of this safety recall by way of established communication methods. This recall is estimated to launch in 3rd Quarter of 2022.

We ask that you please take the time to ensure that your personnel are aware of this communication and are prepared to execute a customer friendly process for inquiries regarding involved vehicles.

Customer Services Field Operations  
FCA US LLC