News Channel Update | Vans Customer Service and Parts

TO: Freightliner Principals, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Anthony Washington, Department Manager, Regulations and Certifications
Re: Initial Recall Campaign Notification Model 907 (Sprinter) Model Years 2021 Replace Tire and Loading Information Label	DATE: February, 2022



IMPORTANT RECALL CAMPAIGN INFORMATION

Please see the attached documents related to the campaign listed above

News Channel Update | Vans Customer Service and Parts

Campaign No. :	Campaigr	Desc. :		
2022020016p	PDGRE5	BHIN	Replace Tire and Loading Information Label	
This is to notify you of a pending Recall Campaign to replace tire and loading information label on approximately 254 MY21 Freightliner Sprinter vans. The recall campaign will be visible on the www.safercar.gov website and may generate questions from customers. All affected VINs will be flagged as "PENDING" in VMI and cannot be sold.				
Background				
Issue	Mercedes-Benz AG ("MBAG"), the manufacturer of Freightliner vans, has determined that on certain 907 (VS30) platform Sprinter vehicles, the tire and loading information label on the B-pillar could contain erroneous values that overstate the Gross Vehicle Weight Rating. Due to erroneous values for the maximum permissible combined vehicle weight on the tire and loading information label on the B-pillar, overloading of the vehicle could exceed the permissible total weight. As a consequence, over time, this could cause excessive tire wear and in a worst case scenario, could lead to tire failure, which could increase the risk of a crash.			
What We're Doing	DVUSA is conducting a voluntary recall. An authorized Freightliner Sprinter dealer will check the tire and loading information label and replace it with a corrected label. Additionally, a visual inspection of the tires for excessive wear will be conducted. If necessary, tires with excess wear will be replaced on the affected axles.			
Parts	Parts are not yet available			
			hicles Affected	
Vehicle Model Year(s)	Model Year 2021			
Vehicle Model	Sprinter VS30, Platform 907			
		Veh	icle Populations	
Total Recall	254			
Dealer Inventory	1			
Given this notice, it is <u>a violation of Federal Law</u> for a dealer to sell or lease any <u>new</u> Sprinter vehicles in dealer inventory covered by this notification until the vehicle has been repaired.				
Loaner and demonstrator vehicles may continue to be driven, but must not be retailed until repaired.				
Additionally, given this notice, it is <u>a violation of Federal Law</u> for rental companies to rent new Sprinter vehicles covered by this notification until the vehicle has been repaired.				
Next Steps/Notes				
Customer Notification Timeline An o		An owner noti	n owner notification letter will be mailed in March, 2021.	
AOMS/SOMS AOMs – This recall may notice to your dealers			ecall may generate questions from your dealers. Please forward this r dealers ASAP.	
Rental Fleet Partners fleet representa		fleet represer	r affect vehicles in your fleet. Please contact your respective DVUSA ntative for further information and next steps. For repairs, please preferred DVUSA dealer.	
While we regret any inconvenience this may cause, we are determined to maintain a high level of vehicle quality and customer satisfaction.				