News Channel Update | Vans Customer Service and Parts

TO: Freightliner Principals, General Managers, Sales Managers, Service Managers, Parts Managers	FROM: Anthony Washington, Department Manager, Regulations and Certifications
Re: Initial Recall Campaign Notification Model 907 (Sprinter) Model Years 2019-2021 Update Rear View Camera Software	DATE: May, 2022



IMPORTANT RECALL CAMPAIGN INFORMATION

Please see the attached documents related to the campaign listed above

News Channel Update | Vans Customer Service and Parts

Campaign No. :	Campaign Desc. :	Hadata Baan Viene Comerce Coftware	
2022040016p	PDGKOMRUE	Update Rear View Camera Software	
Freightliner Sprinter v		date the Rear View Camera software on approximately 690 MY19-20 visible on the www.safercar.gov website and may generate questions from "in VMI and cannot be sold.	
	Background		
Issue	Mercedes-Benz AG ("MBAG"), the manufacturer of Freightliner Sprinter vans, has determined that on certain Sprinter vehicles, the display function of the rearview camera might be impaired. In some instances the rearview image might not be displayed in the central display after engaging the reverse gear. Instead, the central display would continue to display the existing screen image (e.g. navigation, radio, etc.) or display a black screen with a message warning of the inoperability of the rearview camera to display an image. There is no deactivation of the rearview camera, or frozen rearview camera image. A rearview camera image might not be available within 2.0 seconds (as required by FMVSS 111 S5.5.3) as the vehicle begins to back up, which might impair rear visibility which could increase the risk of a crash.		
What We're Doing	DVUSA is conducting a voluntary recall. An authorized Freightliner Sprinter dealer will update the software for the rearview camera to current product specifications.		
Parts	Parts are not available		
Vehicles Affected			
Vehicle Model Year(s)	Model Year 2019-2020		
Vehicle Model (s)	Sprinter VS30, Platform 907		
Vehicle Populations			
Total Recall	690		
Dealer Inventory	0		
Given this notice, it		a dealer to sell or lease any <u>new</u> Sprinter vehicles in dealer inventory ation until the vehicle has been repaired.	

Loaner and demonstrator vehicles may continue to be driven, but must not be retailed until repaired.

Additionally, given this notice, it is <u>a violation of Federal Law</u> for rental companies to rent new Sprinter vehicles covered by this notification until the vehicle has been repaired.

Next Steps/Notes		
Customer Notification Timeline	An owner notification letter will be mailed in June, 2022.	
AOMS/SOMS	AOMs – This recall may generate questions from your dealers. Please forward this notice to your dealers ASAP.	
Rental Fleet Partners	This recall may affect vehicles in your fleet. Please contact your respective DVUSA fleet representative for further information and next steps. For repairs, please contact your preferred DVUSA dealer.	

While we regret any inconvenience this may cause, we are determined to maintain a high level of vehicle quality and customer satisfaction.