


Safety Recall 22KWJ: Meritor Tie Rod Clamps

 [Edit](#)  [Clone](#)

Number

22KWJ / 22V782 / 2022-592

Supplier

Meritor

Description

Safety Recall 22KWJ: Meritor Tie Rod Clamps

Date

11/1/2022

What's New

Safety Recall – Interim Notification Certain Meritor tie rod clamps are subject to cracking due to heat treatment issues during manufacturing. Clamp fracture could lead to tie rod separation from the cross tube and partial loss of vehicle steering capability, increasing the risk of a crash. This bulletin will be updated when repair parts and procedures are available.

Introduction

Certain Meritor tie rod clamps are subject to cracking due to heat treatment issues during manufacturing. Clamp fracture could lead to tie rod separation from the cross tube and partial loss of vehicle steering capability, increasing the risk of a crash. Drivers and service personnel may notice a loss of vehicle alignment preceding a complete fracture of the clamp.

Situation

83 (39 US and 44 CAN) Model Year 2023 T370, T480, T800, T880, W900, and W990 chassis built from 01/05/2022 through 06/22/2022.

Resolution

Safety Recall

This Interim Notification will be updated when parts and repair procedures are available.

Federal Law

It is a violation of Federal law for a dealer to sell or lease new vehicles covered by this recall until the defect or noncompliance has been corrected.

Links

[Chassis List](#)

Authored by: JB3